

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

DT588
NE
1/2-1
0.885 mi.
4671 ft.

MANHOLE 59276
AVE X & E 2ND ST
BROOKLYN, NY

NY Spills S103573737
N/A

Site 2 of 2 in cluster DT

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: MANHOLE 59276
Address: AVE X & E 2ND ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9809643 / 2002-11-04
Facility ID: 9809643

Facility Type: ER
DER Facility ID: 257236
Site ID: 319297
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1998-11-02
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1998-11-02
CID: 195
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-11-02
Spill Record Last Update: 2002-11-08
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: RICHARD ROACH
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

ENGELHARDT 11/13/98 - Saccacio - General Info: 300 gallons of water.
Containment: Yes, in manhole. Oil containing equipment in manhole:
Unknown feeder type Cleanup Plan: The sample was taken and results
came back as <1 ppm PCB's. Cleanup is pending equipment availability.
-sps 11-02-98 01:25 S. DONTONE 49649 MECH A FLUSH OPERATIONS FOUND
APPROX 1 QT OF UNKNOWN OIL IN MH 59276 ON APPROX 300 GAL OF WATER. NO
SEWERS OR WATERWAYS EFFECTED AND IS CONTAINED. TOOK SAMPLE W/4-6 HRS
PRIORITY-PLACED ENV STOP TAG# 03469 UPDATE: 11/2/98 LAB RESULTS: <1.0
PPM-JAPOVERELLI-56037 UPDATE: 11/3/98 05:25- HUFORD-74294 REPORTS
CLEANED-UP WITH SLIX AND STAG# 03469 REMOVED INCIDENT IS CLOSED."
"Unknown type oil found in manhole. Approx 1 quart total. Sample
taken. Con Ed spill number 120961. No call back necessary."

All Materials:

Site ID: 319297
Operable Unit ID: 1070716
Operable Unit: 01
Material ID: 313544
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported